

Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.	Part No. Replacement No. Mfr.
BC377 2N2222 3 PHIN 2N2483 3 PHIN 2N4401 3 MOTA BC337 3 PHIN BCX19 3 PHIN BCX54 3 PHIN THBC337 3 SPR THBC635 3 SPR	BC396 (Cont'd) THBC640 3 SPR BC397 2N2904A 1 PHIN THC2904A 3 SPR TP2904A 3 SPR BC398 2N2218A 1 PHIN GES2218A 3 GESY THC2218A 3 SPR TN2218A 3 NSC TP2218A 3 SPR	BC420 BC693 1 SGSI BC425 BC337 1 PHIN BC337 3 SGSI BCX19 3 PHIN THBC337 3 SPR BC427 BC327 1 PHIN BC297 3 SGSI BCX17 3 PHIN THBC327 3 SPR BC429 BC440 1 SGSI BC635 3 PHIN BC430 BC460 1 SGSI 2N5323 3 RCA BC431 BC301 1 SGSI 2N699 3 RCA BD139 3 PHIN D40D7 3 GESY BC432 BC303 1 SGSI 2N4314 3 RCA BD140 3 PHIN BC437 BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR BC438 BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR BC439 BC109 1 SGSI BC549 1 PHIN BCF32 3 PHIN THBC109 3 SPR BC440 BC635 1 PHIN 2N5321 3 RCA BC377 3 SGSI BC868 3 PHIN BCX54 3 PHIN THBC368 3 SPR THBC635 3 SPR BC441 2N5320 1 RCA BC637 1 PHIN BCX55 3 PHIN DE128 3 DGE MPSA06 3 MOTA THBC637 3 SPR BC446 BC477 1 SGSI BC640 3 PHIN BC448 BC477 1 SGSI BC640 3 PHIN BC451 BC107 1 SGSI BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR BC452 BC108 1 SGSI THBC108 3 SPR BC453 BC109 1 SGSI BCF32 3 PHIN THBC109 3 SPR BC454 BC177 1 SGSI BC557 1 PHIN BC478 3 SGSI BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR BC455 BC178 1 SGSI BC858A 3 PHIN THBC178 3 SPR BC456 BC179 1 SGSI BC859A 3 PHIN BCF29 3 PHIN THBC179 3 SPR BC457 BF336 3 PHIN BC460 2N5323 1 RCA BC869 3 PHIN D43C7 3 GESY	BC460 (Cont'd) DE129 3 DGE THBC369 3 SPR BC461 2N5322 1 RCA D42C8 3 GESY DE129 3 DGE BC467 BC107 1 SGSI BC547 1 PHIN BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR THBC547 3 SPR BC468 BC108 1 SGSI BC548 1 PHIN THBC108 3 SPR THBC548 3 SPR BC469 BC109 1 SGSI BC549 1 PHIN BCF32 3 PHIN THBC109 3 SPR BC477 BC640 1 PHIN 2N2907A 3 PHIN BC177 3 PHIN BC556 3 PHIN BC557 3 PHIN BC856A 3 PHIN BCX53 3 PHIN THBC556 3 SPR THBC640 3 SPR BC478 BC557 1 PHIN 2N2484 3 PHIN BC558 3 PHIN BC558B 3 PHIN BC858A 3 PHIN BC860A 3 PHIN BC875A 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC557 3 SPR BC479 BC557 1 PHIN BC478 3 SGSI BC559 3 PHIN BC859A 3 PHIN BC875A 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC557 3 SPR BC485 THBC485 1 SPR BC485A THBC485A 1 SPR BC485B THBC485B 1 SPR BC507 BC639 1 PHIN BCX56 3 PHIN THBC639 3 SPR BC508 BC637 1 PHIN BCX55 3 PHIN THBC637 3 SPR BC509 BC637 1 PHIN BCX55 3 PHIN THBC637 3 SPR BC512 BC177 1 SGSI BC327 1 PHIN BC297 3 SGSI BC875A 3 PHIN BCX17 3 PHIN BCX71G 3 PHIN BCX71H 3 PHIN BCX71J 3 PHIN BCX71K 3 PHIN THBC177 3 SPR THBC327 3 SPR BC513 BC178 1 SGSI BC328 1 PHIN BC298 3 SGSI BC858A 3 PHIN BCX18 3 PHIN THBC178 3 SPR THBC328 3 SPR BC514 BC179 1 SGSI BC328 1 PHIN BC298 3 SGSI BC859A 3 PHIN	BC514 (Cont'd) BCF29 3 PHIN BCX18 3 PHIN THBC179 3 SPR THBC328 3 SPR BC516 THBC516 1 SPR BC517 THBC517 1 SPR BC520 BFY76 1 SGSI 2N2484 3 PHIN BC521 BFR17 1 SGSI BC522 BFR17 1 SGSI BC523 BFY76 1 SGSI 2N2484 3 PHIN BC524 BC107 1 SGSI BCX70G 3 PHIN BCX70H 3 PHIN BCX70J 3 PHIN BCX70K 3 PHIN THBC107 3 SPR BC542B MPS6521C 3 SPR BC546 THBC546 1 SPR BC107 3 SGSI BC182L 3 SPR MPS8598 3 MOTA THBC182 3 SPR BC546A BCV71 1 PHIN THBC546A 1 SPR BC546B BCV72 1 PHIN THBC546B 1 SPR BC547 BCX70G 1 PHIN BCX70H 1 PHIN BCX70J 1 PHIN BCX70K 1 PHIN THBC547 1 SPR 2N697 3 RCA 2N706A 3 MOTA 2N2221 3 MOTA 2N2221A 3 PHIN BC107 3 PHIN SGSI BC109 3 SGSI BC147 3 PHIN BC183L 3 SPR BC378 3 SGSI BCW72 3 MOTA BFY76 3 SGSI BSS81B 3 SIEG D45C6 3 GESY DE123 3 DGE DE123A 3 DGE DE123AP 3 DGE DE161 3 DGE DE289A 3 DGE MMBT3904 3 MOTA MMBT6428 3 MOTA MMBT6429 3 MOTA MMBTA20 3 MOTA MPS6513C 3 SPR PN100 3 NSC SC237 3 MIKG SD1310 3 THCS THBC167 3 SPR THBC183 3 SPR THBC237 3 SPR THBC317 3 SPR THC3825 3 SPR THC4123 3 SPR BC547A BCW71 1 PHIN THBC547A 1 SPR 2N930 3 SGSI BC107 3 SGSI BC107A 3 PHIN BC140 3 SGSI BC298 3 SGSI BCW60D 3 SIEG BCY59 3 SGSI BF196 3 PHIN BFY76 3 DGE DE123A 3 DGE DE123AP 3 DGE DE289A 3 DGE MMBT2369 3 MOTA PN3691-18 3 NSC PN3692-18 3 NSC SCE238 3 MIKG THC2712 3 SPR THC2714 3 SPR THC3392 3 SPR THC3393 3 SPR THC3394 3 SPR THC3396 3 SPR THC3397 3 SPR THC3691 3 SPR THC3692 3 SPR THC3693 3 SPR THC3694 3 SPR THC3695 3 SPR THC3696 3 SPR THC3697 3 SPR THC3698 3 SPR THC3699 3 SPR THC3700 3 SPR THC3701 3 SPR THC3711 3 SPR THC5210 3 SPR THC5219 3 SPR BC547C BCW81 1 PHIN BC548 BC108 1 SGSI THBC548 1 SPR 2N706 3 MOTA 2N3440 3 MOTA 2N3903 3 GESY BC108 3 PHIN BC109 3 SGSI BC148 3 PHIN BC549 3 PHIN BSS81C 3 SIEG DE123A 3 DGE DE123AP 3 DGE MPS6514C 3 SPR PN100 3 NSC THBC108 3 SPR THBC168 3 SPR THBC318 3 SPR THC4124 3 SPR TMPT4124 3 SPR BC548A BCW31 1 PHIN BCW60A 1 PHIN THBC548A 1 SPR 2N27AA 3 GESY 2N2222 3 SGSI BC107 3 SGSI BC108 3 SGSI BC108A 3 PHIN BCY58 3 SGSI BCY59 3 SGSI BF196 3 PHIN BF198 3 PHIN DE123AP 3 DGE DE199 3 DGE DE289A 3 DGE MMBT2369 3 MOTA PN3691-18 3 NSC PN3692-18 3 NSC SCE238 3 MIKG THC2712 3 SPR THC2714 3 SPR THC3392 3 SPR THC3393 3 SPR THC3394 3 SPR THC3396 3 SPR THC3397 3 SPR THC3691 3 SPR THC3692 3 SPR THC3693 3 SPR THC3694 3 SPR THC3695 3 SPR THC3696 3 SPR THC3697 3 SPR THC3698 3 SPR THC3699 3 SPR THC3700 3 SPR THC3701 3 SPR THC3711 3 SPR THC5210 3 SPR TMPT3903 3 SPR TP3691 3 SPR TP3692 3 SPR BC548B BCW32 1 PHIN BCW60B 1 PHIN BCW60C 1 PHIN THBC548B 1 SPR BFY76 3 SGSI DE199 3 DGE SCE238 3 MIKG THC2926 3 SPR THC3391 3 SPR THC3395 3 SPR BC548C BCW33 1 PHIN		